



Lead



**SAMPLE HAZARDS:**

Working on ladders or scaffolding at heights; working in a cramped or restrictive work chamber; working around and with machinery having moving parts; electrical power supply and high voltage; and cuts from tools or materials.